

Meeting at Great Bowden Cemetery. 10am 16 December 2008

Subject. To view results of primary works completed recently in and around the cemetery.

Attending. Ms Caroline Averill and Mr Alf Herbert.

Item.

The watercourse, culvert head, and the trench fill in field.

*Agreed the watercourse (attendance to deepening, also the spoil to trench wants levelling over the now settled trench.*

The cattle bridge adjacent to corner of cemetery.

*Was viewed concluding that deepening was required.*

The heaped spoil along the bottom boundary of the burial ground & overspill into the watercourse!

*Refers to John Parrott.*

Ground condition where standing water had been in evidence during recent years.

*Agreed. No evidence of reoccurrence to date.*

The tree stumps same area.

*Refers to John Parrott.*

The Long Brick Wall. Settlement at the lower end and the amount of lean into the burial ground.

*The wall is under a survey to be prepared. Capitol to be applied*

*For.*

The roots of severed ivy and those of rogue self sets ie, Ivy, Ash, Elder, and bramble.

*Survey and Capitol as previous para.*

Wall to waste ground,

*Agreed that to reinstate a lintel to comply with Building regs.*

*Re setting the lintel it will be at a higher level.*

The entrance gates, Front Wall, and the new drainage on Dingley Road that leads into the side ditch.

*The wall and gates are in a works programme for repair.*

Trees a further two or three are dieing off?

*2010 these will be viewed for felling if no regeneration occurs.*

The side hedge, recently trimmed early Spring 2007.

*Hedgelaying by a voluntary party could be accepted by H.D.C.*