

**3 February 2008**

**Up date re Great Bowden Cemetery - Gunnsbrook Gusher**

Voluntary Inspection, Dye Test, Report.

Findings of dye test.

From the Knights End Road storm inspection chamber located in the field a dozen paces or so south of the cemetery boundary, a square shaped cover. Dye dropped here passed through the Dingley road foul chamber junction quite clearly indicating to be of close proximity to the Gunnsbrook culvert underneath.

In the field near the cemetery corner a triangular inspection cover, tested the depth to be 2.8meter approx...

The continued saturation of this field etc. points to a temporary diversion of this watercourse into the storm chamber near by, thus allowing the drain off to happen in Cemetery and field alike.

**Recommendation**

David French gives a considered opinion. That a new pipe is introduced of a larger section than previous, but at a satisfactory depth to miss the recent storm drain pipe

Link to the Dingley road foul .This may be more economical than the search and find to clear the blocked culvert which appears to be at a greater depth than first thought.

The cattle drinker feed is about three feet below field level before it proceeds under old river bed before discharging into the River Welland.

**Cemetery**

The intolerable conditions experienced by so many visitors during this Christmas to the New Year holiday period should cease.

**Please Note**

David French. Alf. Herbert, are very willing to attend a site meeting in confirmation of these views.

cc. Matthew Bills. Jeremy Greville-Heygate. Tim. Banks. John Hunt. David French. Alistair Swatridge. District Councillor. Natalie Thomson. Compass Group.